

Control of variables

Thickness

TAPPI 411

Required apparatus

- Micrometer.

Analog or digital instrumentation can measure thickness. The device should be set to measure in micrometres.



Description

To obtain accurate results:

- The sides and average width of the material should be measured. This applies to the delivery of both reels and sheets.
- Two measurements of each area should be taken, considering their average.
- To get the final value, calculate the overall average of the three measurements.